



Firestop Education & Committee – Action Conference Seattle, Washington May 1, 2008

Firestop Data Collection,
Maintenance Documents
and
Firestop Contractor Stats

Presented By











The University of Manitoba, Buller Building is located at the Fort Garry Campus in Winnipeg, Manitoba and was originally opened in 1932. This 5 level, 99,400 sq.ft facility services the Biological Faculty. The Firestopping upgrades were phased over 3 years for a value of \$800,000.





Methodology

- Review current drawings and written documents
- Code analysis Fire Separations
- Data Collection / Inventory from existing fire separations
 - Service penetrations M+E
 - Top of wall joints
 - Wall to wall joints
 - Perimeter joints
 - Recessed M+E devices
 - Abandoned openings
 - Extension of walls
 - Floor or wall partition upgrades
- Floor, wall and ceiling schedules
- Bid documents (drawings and specification) are created







Drawing Set Up

 AutoCAD Floor Plans are developed based on the owners most up dated electronic documents

- Existing floors are cleaned up to form the base firestop drawings
- Based on the code analysis, fire separations are indicated on the plans (hourly ratings)
- Reference Numbers are indicated:

o Walls

(1066)

Floors

F229

Ceilings


C116

- Additional keynotes are placed on drawings to suit site conditions
- Building sections, wall sections or sections and details are provide to suit upgrade requirements




















Schedule Setup

- FS Schedule Wall, (Enter)
 - o Reference number
 - o Drawing number
 - o Room number
 - Wall type
 - Photo number
 - Quantity
 - Description
 - o Size
 - FS Detail number
 - o Penetration note



- During Construction, the following data is entered by the FS Contractor
 - ∘ I.D. Plate No. and Design Listing No.





University of Manitoba Req#157C050720-02 FIRESTOPPING SCHEDULE
- WALL

Section 00971

Page 11

11066 F	FSD.1	Corridor	PL CONC		- - - - - - - - - - - - - - - - - - -	2 1 1 1 1 1 1 2 4	SD EMT ABO ABOS EMT SLV CAT5 LV	4" 1/2" 6" 9" 1/2" 1/2"	01.02 01.02 00.04 00.04 01.02 01.02 03.04 03.02		3, 6 1 1 2, 6
1066 F	FSD.1	Corridor	PL CONC		390	1 1 1 1 2 4 4	EMT ABO ABOS EMT SLV CAT5 LV	1/2" 6" 9" 1/2" 1/2"	01.02 00.04 00.04 01.02 01.02 03.04		1 1 2, 6
1066 F	FSD.1	Corridor	PL CONC		390	1 1 2 4	ABOS EMT SLV CAT5 LV	9" 1/2" 1/2" - -	00.04 01.02 01.02 03.04		1 2, 6
1066 F	FSD.1	Corridor	PL CONC		390	1 1 2 4	EMT SLV CAT5 LV	1/2" 1/2" - -	01.02 01.02 03.04		1 2, 6
1066 F	FSD.1	Corridor	PL CONC		390	1 2 4	EMT SLV CAT5 LV	1/2"	01.02 01.02 03.04		1 2, 6
1066 F	FSD.1	Corridor	PL CONC		390	1 1	CAT5 LV	-	03.04		2, 6
1066 F	FSD.1	Corridor	PL CONC		390	1 1	LV	-			
1066 F	FSD.1	Corridor	PL CONC		390	1 1	LA		03.02		
1066 F	FSD.1	Corridor	PL CONC		-	1		35'-7x2"			
					-	1		35'-7x2"			
					-		TOW		-		30, 69, 72
					391	1		35'-7"	09.04		
					391		BOW	35'-7"	09.06E		45
						2	DWP	1"	01.02		
					391	1	ABO	9"	00.04		6
					391	2	ABO	3"	00.04		6
					392	1	ABO	6"	00.04		6
					-	1	SD	3"	08.02		6
					393	1	EMT	1/2"	08.02		6
					393	1	HWP	8"	08.04		6
					393	1	DWP	5"	08.04		6
					-	2	EMT	1/2"	01.02		6
					-	1	ABO	2"	00.02		6
					-	1	BX	-	01.02		6
					394	1	ABOS	4"	00.04		-
					394	1	CORFS	1"	01.02		1
					395	1	HWP	1 1/2"	08.04		9
					395	1	DWP	1 1/2"	08.04		9
					395	2	EMT	1/2"	08.02		9
					395	1	GP	1/2"	08.02		9
					395	1	PVC	1/2"	02.02		9
					395	1	CA	1/2"	08.02		9
			-		393	1	PS	1/2	06.04		- 3
					-	1	JB		06.02		
1067 F	FSD.1	Corridor	PL CONC	No Penet	rations	<u> </u>	JB	-	00.02		
1007	30.1	Corridor	FE CONC	140 i ciicu	lations	1	TOW	35"	09.04	1	
			-		-	1	BOW	35"	09.06E		47
			-		-	1	LA	35"x2'	09.00E		71, 70
1068 F	FSD.1	Stair 130	PL CONC		-		LA	30 XZ			71,70
1000	JD. I	Giali 130	I L CONC			1	TOW	5'-10"	09.04		
			1		-	1	BOW	5'-10"	09.04 09.06E		47
			1		-	1	EMT	1"	08.02		6
			1			1	SB	2"x4"	06.02		-10
1069 F	FSD.1	Stair 130	PL CONC	No Peneti	rations	Ti.	100	4 A+	100.02	1	
1009	JD.I	otali 130	PL CONC	INO FEITEL	adons	1	Tow	13'-10"	09.04	1	
			1			1	BOW	13'-10"	09.04 09.06E		47
1070 F	FSD.1	Stair 130	PL CONC		-	12	DOW	113-10	109.00E	1	141
10/0	JU.I	otali 130	L'E CONC			1	Tow	5'-9"	09.04		
					-	1	BOW	5'-9"	09.04 09.06E		
			1			1	LF	6"	06.02		+
071	FSD.1	Stair 130	PL CONC	No Penat	rations	12	jur.	U	00.02	1	
1071 F	rou.i	Otali 190	PL CONC	INO FEITEL	auons	1	TOW	19'-8"	09.04		
					-	1					47
1070	TOD 4	04-1-400	DI CONTO		-	11	BOW	19'-8"	09.06E		41
1072 F	FSD.1	Stair 130	PL CONC			Ta	TOW	401.011	00.04		
					-	1	TOW	10'-0"	09.04		
					-	1	BOW	10'-0"	09.06E		
					-	1	EMT	1/2"	01.02		
					-	1	CAT5		03.02		





University of Manitoba Reg#157C050720-02 FIRESTOPPING SCHEDULE
- WALL

Section 00971

Page 11


Ref No.	Dwg. No.	Room No.	Wall Type	I.D. Plate No.	Photo No.	Quantity	Description	Size	FS No.	Design No.	Penetration Notes
1066	FSD.1	Corridor	PL CONC		20	- 16	ar		55		ox
					390	1	LA	35'-7x2"			30, 69, 72
					=	1	TOW	35'-7"	09.04		**
					-	1	BOW	35'-7"	09.06E		45
					391	2	DWP	1"	01.02		
					391	1	ABO	9"	00.04		6
					391	2	ABO	3"	00.04	8	6
					392	1	ABO	6"	00.04		6
					ā	1	SD	3"	08.02		6
					393	1	EMT	1/2"	08.02		6
					393	1	HWP	8"	08.04		6
					393	1	DWP	5"	08.04		6
					-	2	EMT	1/2"	01.02		6
					-	1	ABO	2"	00.02	1	6
					-	1	BX	-:	01.02		6
					394	1	ABOS	4"	00.04		
					394	1	CORFS	1"	01.02		1
					395	1	HWP	1 1/2"	08.04		9
					395	1	DWP	1 1/2"	08.04		9
					395	2	EMT	1/2"	08.02		9
					395	1	GP	1/2"	08.02		9
					395	1	PVC	1/2"	02.02		9
					395	1	CA	1/2"	08.02		9
					2	1	PS	2//	06.04		
					-	1	JB	-	06.02		Y

Penetration Note No. 9 – Polyurethane foam present.






Firestop Data Collection Conduits








FS Details












Related Details






DUCT WRAP AT SHAFT WALL



FIRE RATED DUCT WRAP AROUND FUME HOOD PVC DUCTS




SECTION THROUGH FIRE RATED DUCT WRAP AND FUME HOOD DUCT









CGC Building FS Value - \$750,000



MacDonald Building FS Value - \$470,000



Brandon Federal Building FS Value - \$460,000



Parker Building Level 300, 500 FS Value - \$120,000



Government of Canada Building FS Value - \$160,000



Victory Building FS Value - \$250,000







Club Regent Casino FS Value - \$750,000



Jack River School FS Value - \$150,000



Royal Canadian Mint FS Value - \$1,700,000



McPhillips Street Station Casino FS Value - \$825,000



Churchill Town Center FS Value - \$2,300,000









The University of Manitoba, Faculty of Pharmacy building is currently under construction located at the Bannatyne Campus in Winnipeg, Manitoba. This 5 level, 105,000 sq.ft. Pharmacy facility has 3 levels of labs and 1 level of classrooms is being built for a construction cost of \$22.5 Million.





Methodology

- Review current construction documents
- As Builts
 - Drawings
 - Schedules
- Product
 - Literature
 - o MSDS
 - o VOC
 - o Shelf Life
 - Life Expectancy
- Design Listed System
- Final Report
 - o ASTM E2174 & E2393









As Built Drawings

- Create AutoCAD floor plans based on the Architectural Documents
- Floor plans are developed indicating fire separations (as noted on the Architectural Documents) and Reference Numbers:
 - Walls
 - Floors
 - o Ceilings
- Keynotes are placed to provide further info
- Building sections, wall sections, sections or details are provided




















Schedule Setup

- FS Schedule Wall, (Enter)
 - o Reference number
 - Drawing number
 - o Room number
 - Wall type
 - o I.D. Plate number
 - o Photo number
 - Quantity
 - Description
 - o Size
 - Report number (if inspected)
 - o Design number
 - o Penetration note







6009

FIRESTOPPING SCHEDULE
- WALL

Section 00971

Page 1

Ref No.	Dwg. No.	Room No.	Wall Type	I.D. Plate No.	Photo No.	Quantity	Description	Size	Report No.	Design No.	Penetration Notes
0003 FS1.1	FS1.1	058	GB & SS								
				0003.01	-	1	TOW	31'-8"	DR - 1.0	HW-D-0083	-
				-	-	1	BOW	31'-8"	MR - 1.0	BW-S-0002	-
				ā	-	2	W-W	10'-8"	317	WW-D-0040	-
				0003.02	1	1	CIP	4"	GR - 1.0	W-L-1290	25
				0003.03	2	4	EMT	3"	MR - 2.0	W-L-1408	820
				0003.04	2	2	CIP	2"	35 = 3	W-L-5257	0.
				-	3	1	Duct	8"x8"	-	-	-
				0003.05	4	2	CIP	2"	OR - 1.0	W-L-1054	7-7
				0003.06	4	2	S-STL	1"	-	W-L-1054	-
				0003.07	5	2	CIP	2"	7/ 4 /	W-L-1290	1 = 1
				0003.08	5	2	EMT	1"	DR - 3.0	W-L-1290	0.40
					6	1	Duct	8"x8"	9 9	- 0	
				0003.09	7	1	CIP	2"	DR - 2.0	W-L-1290	
				0003.10	7	2	CIP	2"	84	W-L-5257	220
				0003.11	8	1	S-STL	1"	3/ 4 3	W-L-1054	-
				0003.12	9	1	RB		GR - 2.0	CLIV 7	() ·







Photo No. 01



Photo No. 03



Photo No. 02



Photo No. 04



Photo No. 05







Photo No. 06



Photo No. 08



Photo No. 07



Photo No. 09





Final Report

- Introduction
 - Overview
 - Mandate
 - Contact Listing
 - Executive Summary
- Performance Requirements and Verification
 - Method
 - Types of Firestops
 - Redundant Design Listed Systems
 - Quantities of FS per level
 - Certification

Appendix

- A Correspondence
- B Mock-Ups
- C General Reviews / Observations
- D Destructive Tests
- E Mock-Up Summary
- ∘ F Destructive Test Summary
- G As-Built Drawings
- H As-Built Schedules
- I Submitted Design Listed Systems









Study

- Global and Affinity compiled firestop inspection statistics from 2006-2007
- Projects from Eastern United States and Western Canada were used for this study
- Inspections were based on ASTM E2174 and E2393
- 70 Projects were chosen
- 1000 Tests were performed utilizing Observation or Destructive Test review methods
- Firestop Contractors reviewed:
 - FCIA, FM approved Contractors
 - FCIA Contractors
 - Non Firestop Contractors









Design Listings Reviewed

- Total of 985 Design Listings submitted
- Total of 345 Engineered Judgments submitted
- Accuracy of what is installed on site compared to Design Listings submitted:

FCIA, FM96%

o FCIA 76%

○ Non FS 32%

 Accuracy of what is installed on site compared to Engineer Judgments submitted:

o FCIA, FM 93%

○ FCIA 73%

○ Non FS 12%







Inspection groups scope of work increases:

- Education for Non Firestop Contractors
 - o Building Codes
 - o FCIA MOP
 - Specifications and Drawings
 - Numerous General Site Meetings
 - Product
 - Literature
 - MSDS
 - Installation Limitations
 - Design Listings
 - Engineered Judgments
 - Testing Procedures
 - Mock-Ups









Inspection groups scope of work increases:

- Site Issues by the Non-Firestop Contractor
 - Workmanship is very poor
 - Preparation of joint, service penetration or substrate is not being followed
 - Work is only partially complete
 - No Design Listing was submitted for installed system
 - o Design Listing has not been followed
 - Product has expired, frozen, or washed out
 - Seals have been broken
 - No fasteners or incorrect fastener has been installed on collars
 - Inconsistency of actual installer
 - Constantly canceling site reviews
 - Not familiar with code requirements








Additional Inspection Cost for Non FS Contractor

- Education Requirements Increase
- Installation Issues Increase
- More than one Non FS Contractor on a job
- Additional overlap with Designer, Contractor, Sub Trades, AHJ, Owner
- More Reporting
- More follow up on issues (emailing, fax, phone calls)
- Final Reports increase in size

Inspection Group Costs Increase:

50% to 300%

Up and above using a FCIA – FM approved Firestop Contractor











Project Totals for each Firestop Contractor








Total Tested Firestop Systems







Success Rate
































Firestop Education & Committee – Action Conference Seattle, Washington May 1, 2008



6E Hinckley Ave, Suite 206

Ridley Park, PA 19078

Office: 484-494-3168

Fax: 484-494-3198

MLTesche@comcast.net



200 – 4 Fort Street

Winnipeg, Manitoba, R3C 1C4

Office: 204-982-6940

Fax: 484-453-4556

rob@affinityarch.com

www.affinityfirestopconsultants.com

Thank You

