

# The role of Passive F Protection

Dr Gabrielle Peck, BSc (Hons), Ph.D., MRSC,  
Technical Director

# Our mission

- Educate
- Advocate
- Advance the passive fire industry globally



Firestop Contractors International Association



Standards &  
Engagement

bsi.



## FCIA – Where are we?

- ASTM
- ICC
- NFPA
- UL & ULC STP's,
- ASTM
- BSI

**FCIA** A large, bold, black text 'FCIA' with a red flame icon at the end. The flame icon is a stylized red shape with a flame at the top, positioned to the right of the 'A'.

How??

---

**Global Membership**

---

**FCIA Firestop Manual of Practice - MOPs**

---

**Firestop Education Program**

---

**Webinars**

---

**Life Safety Digest**

---

**International Work**

---

**MENA, India, MX, Australia,  
LATAM**

---

**Social Media; LinkedIn**

What  
we do?

**FCIA** 

## **Speak, Write, Advocate, Promote**

- **ICC**
- **CSI**
- **CSC, FFMIA, ON BOA, ON FMIA, RAIC**
- **NFPA, Center for Campus Fire Safety**
- **Code-Fire Officials**
- **Fire Marshals,**

**To educate & advocate  
for the passive fire  
industry**

Free  
resources &  
materials

**Life Safety Digest -free to subscribe**  
(& reach out if you have an interesting article you'd like to see, or write!)

**Manual of Practice**

- Complimentary PDF to Architects & Specifiers with Design Firms, Code Officials, Fire Marshals, Authorities Having Jurisdiction (AHJs), Facility Managers, and select others -contact to see if you qualify.

**Webinars- free to attend!**

**Newsletter- free to subscribe**

*Contact: Info@FCIA.org*

## ADDITIONAL FCIA PRESENTATIONS & PROGRAMS

### 2022

'Protecting Recessed Boxes in Fire-Resistance-Rated Construction' for the NYS Department of Health - VIRTUAL - October 2022

Presented for the NY State Department of Health, Division of Nursing Home and ICF/IID Surveillance

'Design Installation Inspection Maintenance & Management' for the Ontario Building Officials Association - Niagara Falls, ON - July 2022

Presented for the Ontario Building Officials Association

### 2019

'A Study on the 'DIIM' of Firestopping' at the Office of General Services – Albany, NY – September 2019

Presented at the Office of General Services – Albany, NY

'Fire Separations – Fire Resistance & Firestopping Design, Installation, Inspection and Maintenance' at Canada CSC – May 2019

Presented at CSC's Regina Conference

### 2018

Role of Passive Fire Protection Systems in Maintaining Building Fire- & Life-Safety – December 2018

Presented at BNP's Webinar On-Demand

FCIA's 'DIIM' Canada CSC – DECEMBER 2018

[Newsletter](#)

[Presentations](#)

[07-84-00 Specification](#)

[In Print](#)

[Technical Resources](#)

[Videos & Recordings](#)

[Professional Liability Insurance](#)

[Advertise with FCIA](#)

[FCIA Photo Album](#)

[Archives](#)

[Links](#)

## 07-84-00 SPECIFICATION

[Share this page](#)

The Construction Specifications Institute (CSI) and Construction Specifications Canada documents state, 'State it once, refer to section when needed from other sections'.

### **Penetrations, Joints and Perimeter Fire Containment in One Section – 07-84-00 –**

#### **FCIA ASTM/UL Standards Firestopping Specification:**

- [FCIA 07-84-00 Suggested Spec – PDF](#)
- [FCIA 07-84-00 Suggested Spec – WORD](#)

#### **FCIA Canada Standards Specification – English**

- [FCIA 07-84-00 CANADA Suggested Spec – ENGLISH PDF](#)
- [FCIA 07-84-00 CANADA Suggested Spec – ENGLISH WORD](#)

#### **FCIA Canada Specification – French – Updated September 2019**

- [FCIA 07-84-00 CANADA Suggested Spec – FRENCH PDF](#)
- [FCIA 07-84-00 CANADA Suggested Spec – FRENCH WORD](#)

**As a service to the industry, FCIA offers the [FCIA Manual of Practice\\*](#) **FREE** to:**

- Architects with Design Firms
- Specifiers in practice with Architectural Firms
- Governmental AHJ Building Officials
- Governmental AHJ Fire Marshals, Fire Service, and Fire Officials
- Government Officials

To see if you qualify, email [Cathy@FCIA.org](mailto:Cathy@FCIA.org), including name, job title, company, address, phone, fax and email.

**\*Note: The FCIA Firestop Materials & Systems Guide Manual is NOT part of the FREE MOP offer.**

# TECHNICAL RESOURCES

[Share this page](#)

## FCIA Standard Answer Series, Technical Resources from the FCIA Firestop Manual of Practice, and More...

Below you will find additional technical resources for the industry. Follow the links to read the document online or download in MS Word format.

### Position Papers

[The Global Language of Passive Fire Protection: Understanding the 'DIIM™ Way](#)

### Technical Info – General

[Using Contracts to Manage Volatile Material Availability and Pricing, June 2021](#)

[Managing Volatile Materials Pricing, April 2021](#)

### Technical Info – General Firestopping


[ASTM E3456 - Standard Practice for On-Site Identification of Firestop Systems and Judgements](#)

© 2021 FCIA. All rights reserved. FCIA.org/2020

**DESIGN**  
Specs, Code

**INSTALLATION**  
FM 4991/UL QFCP  
Programs AND Mfr.  
Education

**PFP/BARRIERS**  
**MAINTAIN**  
**PROTECTION**  
Fire Codes



**INSPECTION**

IBC Ch. 17 -NFPA 80 - NFPA 1

# FCIA - Firestop Contractors International Association

**Efforts to expand and share knowledge:**

- India
- United Arab Emirates
- Qatar - Doha
- Canada
- Mexico
- Saudi Arabia
- Australia & New Zealand (FPA NZ, FPA AUS MOU)

# Events:

## FCIA-NFCA PFPCon '26 Dubai

**PFPCon '26 DUBAI**

12-14 JANUARY 2026

DUBAI WORLD TRADE CENTRE

**FCIA** 

**NFCA** 



**Dubai World Trade Centre  
Dubai, UAE**

**12-14 January 2026**

FCIA and NFCA join forces with Intersec Dubai for **PFPCon '26 Dubai**, the FCIA-NFCA Passive Fire Protection Symposium Dubai and the **FM & UL Firestop Exams**.

Attend this event for technical education focused on all aspects of the structural fire-resistance and effective compartmentation industries.

# Upcoming events:

**PFPCon '26**

**The Passive Fire Protection  
Conference & Expo**



**The Aria Hotel & Casino  
Las Vegas, NV**

**March 30-April 3, 2026**

Introducing **PFPCon**, the world's *only* conference dedicated entirely to Passive Fire Protection.

PFPCon '26 joins the FCIA Education & Committee Action Conference and the NFCA Week of Learning and brings together the structural fire-resistance and effective compartmentation industries for a dynamic tradeshow, compelling industry education, high-energy networking events, the FM & UL Firestop Exams and NFCA Fireproofing Exams, and the industry's most interactive Committee Meetings.

This first-ever, one-of-a-kind global gathering is set to ignite the PFP community with unmatched access, unmatched expertise, and an experience so compelling that those involved in the 'D'esign, 'Installation, 'Inspection, and 'M'aintenance of Passive Fire Protection systems will have serious FOMO.

**AKA "the Mother-Con"**

# Upcoming events:

## **FCIA-NFCA PFP '26** **Canada**



**Delta Dartmouth**  
**Dartmouth, NS**  
**September 1-4, 2026**

FCIA and NFCA join forces once again for PFP '26 Canada, the FCIA-NFCA Passive Fire Protection Canada Conference.

Stay Tuned for More Information

# Upcoming events:

**FIC '26**

**FCIA Firestop Industry  
Conference & Trade Show**



**Omni Fort Worth  
Fort Worth, TX**

**November 2-5, 2026**

Stay Tuned for More Information

Thank you to Friends, members and  
supporters of  
FCIA & NFCA

&

## FCIA 2025 Board of Directors


+Corey Beckett (as of  
2026)




# The role of Passive F Protection

Dr Gabrielle Peck, BSc (Hons), Ph.D., MRSC,  
Technical Director

# Smoke toxicity is the leading cause of death in fire.



# UK Statistics: Non fatal injuries in fire



## **NFPA: USA Fire statistics**

### **Structural fires & structural deaths**


#### **Definitions:**

Structural deaths refer to civilian fatalities occurring in structure fires.


A structure fire is defined as any fire in or on a building or other structure, even if limited to contents.

These account for the majority of U.S. fire deaths, with home structure fires causing about 92% of them.


**NFPA: USA Fire statistics**  
**Structural fires & structural deaths**



**NFPA: USA Fire statistics**  
**Structural fires & structural deaths**



**NFPA: USA Fire statistics**  
**Structural fires & structural deaths**



**This isn't a new  
problem...**

# Daeyeonggak Hotel Fire, Seoul, South Korea

25<sup>th</sup> Dec. 1971

Cause: Propane gas explosion  
in a second-floor coffee  
shop.

The blaze rapidly ascended  
the 22-story structure due  
to **combustible cladding** and  
**absent sprinklers**; **smoke**  
**infiltrated stairwells** and  
**upper-floor rooms**, causing  
asphyxiation far from the  
origin.

Evacuation was chaotic amid  
poor exits.

**Casualties:** 164 deaths  
(primarily smoke  
inhalation), 63 injured.



# Daeyeonggak Hotel Fire, Seoul, South Korea

25<sup>th</sup> Dec. 1971

Cause: Propane gas explosion  
in a second-floor coffee  
shop.

The blaze rapidly ascended  
the 22-story structure due  
to **combustible cladding** and  
**absent sprinklers**; **smoke**  
**infiltrated stairwells** and  
**upper-floor rooms**, causing  
asphyxiation far from the  
origin.

Evacuation was chaotic amid  
poor exits.

**Casualties: 164 deaths  
(primarily smoke  
inhalation), 63 injured.**



# SiddhARTH CONTINENTAL HOTEL FIRE, NEW DELHI, INDIA

23<sup>rd</sup> Jan. 1986

Cause: Electrical short circuit in basement banquet hall.

Fire **propagated via service shafts** to upper levels; **toxic smoke permeated guest rooms and atriums**, suffocating occupants distant from flames.

Casualties: 38 deaths  
(mostly asphyxiation) 46



# Siddharth Continental Hotel Fire, New Delhi, India

23<sup>rd</sup> Jan. 1986

Cause: Electrical short circuit in basement banquet hall.

Fire **propagated via service shafts** to upper levels; **toxic smoke permeated guest rooms and atriums**, suffocating occupants distant from flames.



No records to demonstrate inspection or compliance

Investigation and government inquiry highlighted systemic lapses in fire safety enforcement.



Casualties: 38 deaths  
(mostly asphyxiation) 46

# Quakers Hill Nursing Home Fire, Sydney, Australia

18<sup>th</sup> Nov. 2011

Cause: Arson by a nurse using accelerant in two spots.

Early-morning fires **spread smoke across wards**; victims in **distant areas died** from inhalation while asleep or evacuating, **despite sprinklers activating.**



# Quakers Hill Nursing Home Fire, Sydney, Australia

18<sup>th</sup> Nov. 2011

Cause: Arson by a nurse using accelerant in two spots.

Early-morning fires **spread smoke across wards**; victims in **distant areas died** from inhalation while asleep or evacuating, **despite sprinklers activating**.



No records to demonstrate pre-fire inspection or compliance.

Investigation showed:

-Poor design of passive elements.




# Grenfell Tower Fire, London, UK

14<sup>th</sup> June 2017

Cause: Faulty refrigerator ignition on the 4th floor.

Flames spread upward via combustible cladding; **toxic smoke filled the single stairwell** and infiltrated higher-floor apartments, **asphyxiating residents distant from the origin** before flames arrived.

Casualties: 72 deaths (primarily smoke inhalation), 70+ injured.



# Grenfell Tower Fire, London, UK

14<sup>th</sup> June 2017

Cause: Faulty refrigerator ignition on the 4th floor.

Flames spread upward via combustible cladding; **toxic smoke filled the single stairwell** and infiltrated higher-floor apartments, **asphyxiating residents distant from the origin** before flames arrived.

Casualties: 72 deaths (primarily smoke inhalation), 70+ injured.



# Loafers Lodge Fire, Wellington, New Zealand

16<sup>th</sup> May 2023

Cause: Arson; resident with schizophrenia set two fires.

Blaze in 92-bed hostel  
**spread smoke via  
corridors, asphyxiating  
tenants in remote rooms**  
before flames reached them.



**Casualties: 5 deaths  
(smoke inhalation), 20**

# Loafers Lodge Fire, Wellington, New Zealand

16<sup>th</sup> May 2023

Cause: Arson; resident with schizophrenia set two fires.

Blaze in 92-bed hostel  
**spread smoke via  
corridors, asphyxiating  
tenants in remote rooms**  
before flames reached them.



Under investigation

Had a BWOF

Casualties: 5 deaths  
(smoke inhalation), 20

# Valencia Residential Complex Fire, Valencia, Spain

22<sup>nd</sup> FEB. 2024

Cause: Electrical fault in basement transformer room.

Flames climbed via flammable cladding; **toxic smoke permeated all 14 stories**, causing fatalities on distant floors.



Casualties: 10 deaths (primarily smoke inhalation) 15

# Valencia Residential Complex Fire, Valencia, Spain

22<sup>nd</sup> FEB. 2024

Cause: Electrical fault in basement transformer room.

Flames climbed via flammable cladding; **toxic smoke permeated all 14 stories**, causing fatalities on distant floors.



Non-compliant cladding (PU)

Enforcement cited as a failure.




Casualties: 10 deaths (primarily smoke inhalation) 15

# Hotel Oriente in San José, Costa Rica

Ca<sup>nd</sup>use: Under investigation. Serious safety failures revealed, including an emergency exit blocked with metal wire.

The fire started on the third floor of a three-story building in downtown San José. **Fire and smoke spread rapidly, trapping occupants due to the obstructed exit.**



**Casualties: 5 deaths (3 men and 2 women, including children)**

# Hotel Oriente in San José, Costa Rica

Ca<sup>nd</sup>use: Under investigation. Serious safety failures revealed, including an emergency exit blocked with metal wire.

The fire started on the third floor of a three-story building in downtown San José. **Fire and smoke spread rapidly, trapping occupants due to the obstructed exit.**



**Casualties: 5 deaths (3 men and 2 women, including children)**

# Tai Po, Hong Kong, 2025

November 26, 2025

Cause: Nylon netting on building caught fire. Renovation conditions inspected **16 times** in **1.5 years**. Issued improvement notices, including:

- three prosecutions for safety violations
- fines up to HK\$18,000.

Residents complained about safety conditions.



What can we establish from these fires?

- Despite advancements, people are still dying in fires

# What can we establish from these fires?

- Despite advancements, people are still dying from in fires
- Despite there being less fires, the risk level is just as high

# What can we establish from these fires?

- Despite advancements, people are still dying from in fires
- Despite there being less fires, the risk level is just as high
- Inspection and Compliance is rarely enforced properly globally



**Back to basics**

# Key elements of a building

Passive fire protection (PFP) relies on integral building elements to:

- **resist fire spread**
- **maintain structural stability**
  - **control smoke spread**

- Structural Framework
- Compartmentation Barriers
- External Envelope
- Service Integrations




# We rely on the structure remaining stable so that we can:

- Maintain safe egress
- Maintain safety of firefighters
- Maintain safety of the nearby area


• Maintain continuity of the fire barriers in place

• Maintain compartmentation



What would happen if an  
unprotected building  
caught fire?

# Fire stages and development



- Flashover is the rapid transition in a fire where all combustible materials in an enclosed space ignite nearly simultaneously due to intense heat, typically occurring when temperatures reach 500–600°C (932–1112°F), causing a sudden spread of flames and extreme danger.



# 0 to 5 mins


A small fire in a room begins.




5-15 mins



The fire will  
continue to grow...





15-20 mins












**Structural Instability begins  
(20-30 min).**




20-45 mins







## Decay (>45 min)



No protection  
causes 3 key  
problems:

- **Smoke spread**
- **Flame spread**
- **Risk of  
structural  
collapse**




“It’s OK- we don’t need passive fire protection if we have sprinklers...”

Ignition (0-5 min): Flame sparks and a small fire starts



Detectors sense 68°C rise and the alarms start. Evacuation begins, but smoke still spreads and rises.






If the fire is small, and located near the sprinklers- the fire will be put out by the sprinklers. Water mist also aerosolizes smoke, aiding smoke spread

.....But what if the fire is large, or if it is fast growing?

For very large fires or rapidly growing fires, sprinklers may activate but become overwhelmed.

Water mist can further aerosolize smoke, exacerbating toxicity and visibility issues.




# 5–15 mins

sprinklers activate at 68°C, discharging water, capping fire growth. Flames recede, but water mist aerosolizes smoke, **aiding spread**. Horizontal smoke migration through unsealed doors fills atriums



15–20 mins

**Flashover is mitigated (15-20 min):** sprinklers prevent uniform ignition. BUT vertical shaft convection propels unconfined smoke upward, infiltrating vents.



# Quakers Hill Nursing Home Fire, Sydney, Australia

18<sup>th</sup> Nov. 2011

Cause: Arson  
by a nurse  
using  
accelerant in  
two spots.

Early-morning  
fires **spread**  
**smoke across**  
**wards;**  
victims in  
**distant areas**  
**died** from  
inhalation  
while asleep  
or  
evacuating,  
**despite**  
**sprinklers**  
**activating.**

Casualties:



## Fully Developed (20-45 min)

Localized to origin room, **heat begins to warp steel columns (concrete may spall)**.

No collapse imminent, but smoke permeates floors of the building and oxygen dips to 12%. Sprinklers wet distant areas, BUT occupants ARE STILL AT RISK from inhalation.

Smoke flood exit ways, making escape difficult.





# >45 mins

Water suppression douses embers.

Large volumes of smoke are produced. As there is no compartmentation, smoke travels through the building, flooding egress routes.

Those unable to escape unassisted are at risk of incapacitation and are reliant on rescue from firefighters.



# Sprinklers

The statistics



**Sprinklers are effective 89% of the time**

Key cause of failure:  
-Delayed onset/non-operation  
-Fire grew too large too fast, and the  
sprinklers **failed to contain fire**


**The other 11% of the time....?**



No protection causes 3 key problems:

- **Smoke spread**
- **Flame spread** 
- **Risk of structural collapse**

Reduced risk but still a problem if the fire develops rapidly or is <sup>large</sup>.




No protection causes 3 key problems:


- **Smoke spread**
- **Flame spread**
- **Risk of structural collapse**


Active fire protection  
(sprinklers and alarms) stops  
the fire growing too large;

Passive fire protection stops  
the fire and smoke spreading  
around the building






Smoke spread still occurs with sprinklers and alarms!







Smoke will move through openings to other parts of the building.

This is how occupants die in fires despite not being





HVAC systems, Plastic pipes, metal pipes, cables etc..



Solving the problem

# Ignition 0-5 mins

Flame sparks and a small fire starts



## Ignition (0-5 min)

The detectors activate at 60 °C and the alarms activate. Evacuation commences.



# Preventing smoke and flame spread...



# Concept of compartmentation

VS



- Compartmentation should isolate each apartment or designated area – making it as safe as a 2 storey house.
- **This prevents flame spread, and smoke spread.**





#### Rapid Fire Spread

Cladding system contributes to flame spread resulting in risk of multiple simultaneous secondary fires


#### Restricted Fire Spread

Cladding system does not contribute to flame spread. Risk of secondary fires limited







Fire walls



Fire floors



COMPARTMENTS



COMPARTMENT FLOOR



COMPARTMENT FLOOR

COMPARTMENT FLOOR

COMPARTMENT FLOOR

COMPARTMENT FLOOR

COMPARTMENT FLOOR





These buildings will have services that will disrupt compartmentation:

- Plumbing pipes through the floor and walls
- Electric cables through walls, floors, ceilings etc..

**How do we maintain compartmentation when the wall has holes in for services?**



- In façade structures, if the fire reaches the external cladding, an unprotected combustible façade will allow the fire to spread to other floors of a building



Solving the problem:  
Products and Fire rated  
systems

IBC



# **FIRE RESISTANCE**




That property of materials or their assemblies that prevents or retards the passage of excessive heat, hot gases or flames under conditions of use.

How do we achieve this?

# Endothermic materials




(Material decomposes to fuel)





Layer of MO on surface :

- **Radiation shield**
- Continuous barrier to fuel and oxygen




And many other types of products, all with different applications!



# Products & systems

- Ratings quantify a **system's performance** against fire, heat, smoke, and movement.
- A product CAN NOT have a rating. Only a SYSTEM can get rated.



Can not be rated

Can be rated



**SYSTEM Testing = Suitability Statement**

# **Fire Resistance Continuity = SYSTEMS**

- **Structural – SFRM, IFRM, Boards, Wraps....ASTM E119/UL263**
- **Walls/Floors - Fire & Smoke Barriers – Fire Separations**
  - ASTM E119, UL 263
- **Firestopping – Standards are Based on E119, UL 263**
  - UL 1479, ASTM E814, FM 4990, UL 2079, E1966, E2307, E2837, E3037...test
    - methods...”
- **Swinging/Rolling Fire Doors – UL 10B & UL 10C....NFPA 252**
- **Fire Rated Glazing – UL 9, NFPA 257, UL 263, ASTM E119**
- **Fire/Smoke Dampers – UL 555, UL 555S, UL 555C**

What do we assess and why?

Products are applied to an assembly, and THEN tested.


**SYSTEM Testing = Suitability Statement**

# F- rating

- This certifies a firestop's **ability to block flame passage**.
- **This is defined as the Time (in hours) a system prevents flame passage to the unexposed side.**
- Requirements: **Field installs must mirror lab test set up** (e.g., exact fill depth);
- **A 2-hour F means  $\geq 2$  hours before breakthrough.**
- Chosen to match barrier rating (e.g., 2-hr wall



# T-Rating




- The time before unexposed side temperature rises 325°F (163°C) above ambient, plus no flame.
- Selected for occupant protection in escape paths (NFPA 101).
- T-Rating limits heat conduction through the firestop, preventing auto-ignition on the unexposed side (e.g., cables melting, sparking secondary fires).

# L-Rating

- L-Rating: Air leakage rates for smoke seal assess how much smoke will pass through the system.
- It is determined post-fire via blower door test; required for smoke barriers (NFPA 105).
- L-Rating measures air/smoke leakage
- Even F/T-rated systems leak if unsealed—L ensures tenable air for escape.
- Steps:
  - (1) Fire test first
  - (2) Cool, seal chamber
  - (3) Apply pressure, measure flow.
- UL 1479 Annex
- E/ASTM E814 Annex A

# L-Rating



- L-Rating: Air leakage rates for smoke seal



flow.


- Anexo UL 1479
- Anexo A de ASTM E814

- UL 1479 Annex
- E/ASTM E814 Annex A

# M-Rating

Movement: Maximum displacement (mm) in axial/lateral directions while maintaining integrity.

- Tested under cyclic movement; chosen for seismic/dynamic joints (e.g., IBC Table 715.3).
- Selection depends on hazard (e.g., occupancy, penetration type) and codes; e.g., high-rises mandate 2-3 hr F/T.
- M-Rating assesses firestop resilience to building movement (thermal expansion, seismic), preventing cracks that breach seals.
- M=25% means handles 25% annular space shift.



# Choosing a solution...

- The way you pick a solution is dependant on your countries building code and processes.
  - Performance based design
  - Prescriptive based design
  - Objective based
  - Hybrid approaches

# Standard Tests Establish Fire-Resistance


- USA, and North America
  - ASTM E119
  - UL 263
- Canada
  - ULC-S101
- Euro
- ISO 834
  - BS 476/EN 1363
- Australia & NZ
  - AS 1530.4



UL Image

# Time Temperature Curve

## Structural, Compartmentation, Breach




UL 555

Fire, Smoke, Combination, Radiation

– UL 555 Damper Standards

- **UL 555** - standard for Fire dampers
- **UL 555S** - standard for Smoke dampers
- **UL 555C** - standard for Ceiling Radiation dampers
- CAN/ULC-S112, 112.1 (Smoke Control)



Greenheck Image

# Fire Dampers

“A device, installed in an air distribution system, designed to close automatically upon detection of heat, to interrupt migratory airflow, and to **restrict the passage of flame**.” (NFPA 80) –IBC 2024 Section 717



Curtain Fire Damper



True Round Fire Damper



Multi-blade Fire Damper



## Create a Search Now

 Enter file number, CCN, model or




INTERTEK DIRECTORY OF BUILDING PRODUCTS

Listed Products, Code Compliance Research Reports (CCRRs), Certificates of Compliance (COCs), Quality Assurance, and Industry Programs

Company	Nothing selected	▼
ing Category	Nothing selected	▼
CSI Code	Nothing selected	▼
Standard	Nothing selected	▼
Keywords		Spec ID
CCRR #		DOC #
Brand Name		Design Document

Limit results to listings with code compliance research reports (CCRRs)  
 Limit results to listings with certificates of compliance (COCs)

# Tested listed systems .



# C-AJ-1291: During a fire

Through-penetration firestop system for one metallic pipe (EMT or rigid steel conduit, max 4 in. diameter) in concrete floors or walls, achieving 2-hour F/T ratings per ASTM E814/UL 1479.

## Assembly:


- Min 4-1/2 in. (114 mm) thick reinforced lightweight or normal weight (100-150 pcf) concrete floor, or min 5-1/2 in. (140 mm) thick concrete wall.
- Max opening diameter: 4 in. (101.6 mm); max area: 12.6 sq in. (0.0081 m<sup>2</sup>); max dimension: 4 in. (101.6 mm).
- Penetrant: One EMT or rigid steel conduit, rigidly supported on both sides, with annular space 0 to 7/8 in. (22 mm).

## Firestop Materials:

- **Fill, Void, or Cavity Material — Packing:** Mineral wool batt (min 4pcf), 4 in. (102 mm) thick, firmly packed into the annular space. Recessed 1/2 in. (13 mm) from the top surface of the floor or both surfaces of the wall. HILTI CONSTRUCTION CHEMICALS, DIV OF HILTI INC — CP 767 or CP 777 Mineral Wool.
- **Fill, Void, or Cavity Material — Sealant:** Min 1/2 in. (13 mm) thick intumescent sealant applied flush with the top surface of the floor or both surfaces of the wall, overlapping 1/2 in. (13 mm) beyond the perimeter of the opening. HILTI CONSTRUCTION CHEMICALS, DIV OF HILTI INC — FS-ONE MAX or CP 606 Firestop Sealant.


**Certification:** UL Classified for 2-hour F and T ratings.

## Reference: UL Directory




# C-AJ-1291: During a fire

- **Stage 1: Ignition (0-5 min)**
- A localized flame heats the steel pipe, raising its temperature to approx.  $200^{\circ}\text{C}$  ( $392^{\circ}\text{F}$ ) .
- The mineral wool has low thermal conductivity, limiting heat transfer.
- The fire plume rises, producing smoke, but the annular space confinement keeps the unexposed side temperature rise below  $140^{\circ}\text{C}$  ( $284^{\circ}\text{F}$ ) .





# C-AJ-1291: During a fire

- **Stage 2: Growth (5-15 min)**
- Heat increases (approx. 2 MW HRR).
- The mineral wool's ceramic matrix dehydrates endothermically, absorbing heat and releasing water vapor, insulating the pipe (surface typically below 400°C or 752°F).
- No flame passage occurs, maintaining the F-rating.
- The intumescent sealant begins to char, blocking heat and smoke convection.
- The char layer enhances the system's structural stability.




# C-AJ-1291: During a fire

- **Stage 3: Flashover (15-20 min)**
- As temperatures rise, the mineral wool forms an insulating crust (alumina-silica sinters, thermal conductivity  $<0.08 \text{ W/m}\cdot\text{K}$ ).
- The T-rating holds, with the unexposed side below  $181^\circ\text{C}$  ( $358^\circ\text{F}$ ).
- System integrity is maintained: no cracks, minimal smoke leakage (L-rating compliant).



# C-AJ-1291: During a fire


- **Stage 4: Full Development (20-120 min)**
- Under sustained exposure, the char layer from the intumescent sealant and sintered mineral wool prevents autoignition.
- Smoke leakage remains minimal, ensuring safe egress and maintaining the 2-hour F/T ratings.



# C-AJ-1291: During a fire

## During active firefighting, egress and decay

- ✓ The system does not erode
- ✓ 2-hr containment achieved
- ✓ Safe means of egress maintained



C-AJ-1291

The system will perform as tested.....

IF it is designed correctly...  
AND installed correctly...

So what if it  
wasn't?


# C-AJ-1291: During a fire, with fibreglass

- **Substitute Fiberglass for Mineral Wool**
- Replace mineral wool with E-glass fiberglass insulation (**melting**  $\sim 800^{\circ}\text{C}$  or  $1472^{\circ}\text{F}$ ).
- It softens at approximately  $600^{\circ}\text{C}$  ( $1112^{\circ}\text{F}$ ) and melts into a viscous flow at  $\sim 800^{\circ}\text{C}$  ( $1472^{\circ}\text{F}$ ).
- **fiberglass does not char**; it undergoes melting and viscous deformation under fire exposure.




# C-AJ-1291: Substitute rockwool with fibreglass

- Initial insulation holds as temperatures are low, but as heat rises, fiberglass fibres begin to soften (softening point  $\sim 600^\circ\text{C}$ ).
- Minor smoke leakage begins as any organic binders decompose (if present) and fibres start to sink slightly, but the intumescent sealant holds initially ( $T_{-rise} < 140^\circ\text{C}$  on




# C-AJ-1291: Substitute rockwool with fibreglass

- **Stage 2: Growth (5-15 min)**
- Heat intensifies (~700-780°C), causing the fiberglass to soften further and begin melting into glassy droplets.
- Voids form as the material slumps and collapses, allowing convective heat flow.
- Flame starts to penetrate the annular space, compromising the barrier.
- The metal pipe temperature rises rapidly to over 550°C (1022°F).
- The intumescent sealant begins to expand and char, but gaps from melted fiberglass reduce effectiveness.



# C-AJ-1291: Substitute rockwool with fibreglass


- **Stage 3: Flashover (15-20 min)**
- Temperature rise on unexposed side exceeds 180°C (325°F) in under 10 min, failing T-rating.
- F-rating fails due to through-flame passage as melted fiberglass creates openings.
- Smoke leakage surges with potential irritant gases from binder decomposition.



# C-AJ-1291: Substitute rockwool with fibreglass


## Stage 4: Full Development (20-120 min)

- Cascade failure ensues as molten fiberglass flows, exposing more areas.
- Molten glass drips may not ignite adjacent combustibles directly (as glass is non-combustible), but heat transfer accelerates fire spread.
- The unexposed side experiences excessive heat,



# C-AJ-1291: Substitute rockwool with fibreglass

- Material selection must match what has been tested.
  - Thermal/chemical profiles for penetrant-substrate vary;
  - fiberglass is unsuitable for this firestop application.



Incorrect installations, and  
material substitutions will result  
in your “protection” becoming part  
of the problem.





**Combustible foam-  
this will not  
protect the  
penetration.**

**This will generate  
Hydrogen Cyanide on  
burning. This will**

**HCN causes rapid  
incapacitation & death on  
inhalation**

## Material toxicity and combustibility



# Joints and Voids: Head-of-Wall – Mineral Wool and Spray

**System No. HW-D-0300**

October 16, 2015


**Assembly Ratings — 2 and 3 Hr (See Item 3A)**

**Nominal Joint Width — 1 and 2 In. (See Item 3)**

**Class II Movement Capabilities — 25% Compression or Extension**

**L Rating At Ambient - Less Than 1 CFM/Lin Ft**


**L Rating At 400 F - Less Than 1 CFM/Lin Ft**



UL Solutions Image / Text HW-D0300 - Rectorseal

# Joints and Voids


## Head-of-Wall - Intumescent Strips



UL Solutions Image

# Joints and Voids

## Head-of-Wall – Intumescent Strips



**3. Joint System** — Max separation between bottom plane of the floor or roof and top of gypsum board is 1 in. (25 mm). The joint system is designed to accommodate a max 100 percent compression or extension from its installed width. The joint system consists of the following:

**A. Fill, Void or Cavity Material\*** — Factory-supplied intumescent gasket installed and nominally centered over the ceiling runner (Item 2A, 2A1, 2A2, 2A3) prior to attachment to underside of floor or roof assembly. Gypsum wallboard layers to be installed on both sides of the wall maintaining a minimum 1/8 in. (3 mm) overlap over the intumescent gasket at time of installation.

**SPECIFIED TECHNOLOGIES INC** — Speed Flex Track Top Gasket

**C. Forming Material\*** — As an option to Item 3B, preformed mineral wool plugs, formed to the shape of the fluted floor units, friction fit to completely fill the flutes above ceiling runner. The forming material shall be recessed from each surface of wall ceiling runner to accommodate the required thickness of fill material (Item 3D).


**THERMAFIBER INC** — TopStop mineral wool deck plugs Type SAF batts

**D. Fill, Void or Cavity Material\* — Sealant** — Min 1/4 in. (6 mm) thickness of fill material installed on each side of the wall in the flutes of the steel floor or roof deck and between the top of the fill, void or cavity material (Item 3A) and the bottom of the steel floor or roof deck, flush with each surface of wall framing.

**SPECIFIED TECHNOLOGIES INC** — SpecSeal ES Sealant

HW-D-0259

I-Beam to Fluted Deck OVER WALL HW-D-  
0259



# Substitutions

**Substitutions like fiberglass batt are common** because it is a cheaper alternative.

**cheaper ≠ safer**

**This substitution WILL FAIL IN A REAL FIRE.**

**Only use what is specified in the listed system or EJ.**

No protection causes

3 key problems:



- **Smoke spread**
- **Flame spread**
- **Risk of structural collapse**




# Structural instability & protection




# Risk of structural collapse





**Gypsum:  $\text{CaSO}_4 \cdot 2\text{H}_2\text{O}$**



Gypsum:  $\text{CaSO}_4 \cdot 2\text{H}_2\text{O}$

When exposed to high temperatures, the concrete's temperature will rise. As it rises, the **water within the concrete structure will start to evaporate** and leave the structure. This causes the concrete to begin losing its structural integrity. On extreme heating-concrete spalls.




# Structural protection

It is essential for:

insulating bare steel in load-bearing walls


maintaining structural integrity (no buckling)  
(e.g. for 2 hr in high-rises per NFPA 5000).

ASFRMs adheres to irregular steel profiles,  
providing uniform coverage without impeding  
construction, and is mandated by IBC Chapter 7  
for Type I/II buildings to delay critical  
temperature.



# Inherent fire resistance & limitations

- Concrete's low thermal conductivity and high heat capacity naturally resist fire spread, maintaining structural integrity (compressive strength retained up to  $\sim 600^{\circ}\text{C}$  per ASTM E119 testing).



# Types of protection

- **Spray-Applied Fire-Resistive Materials (SFRM)**
- **Intumescent Coatings**
- **Board Systems**
- **Outcome:** Ensures structural stability, limits temperature rise.

Everything has limitations.  
Protection delays the point of failure.





Windsor tower, Madrid, Spain  
12<sup>th</sup> Feb 2005

# Windsor tower, Spain

## 12<sup>th</sup> Feb 2005

- Fire started on the 21st floor (electrical fault)
- Fire grew rapidly in the open-plan office space filled.
- Within an hour, flames engulfed floors above
- Fire **spreading upward at 6-15 minutes per floor** via broken windows and external spill plumes (hot gases rising and igniting above).



# Windsor tower, Spain

## 12<sup>th</sup> Feb 2005


- Downward spread was slower (20-30 minutes per floor)
- fueled by falling debris
- Fueled by radiant heat through the façade
- Spread via internal paths like service voids and unsealed slab-cladding gaps



# Windsor tower, Spain

12<sup>th</sup> Feb 2005

- Lacked operational sprinklers (retrofit)
- Had incomplete firestopping → poor compartmentation.
- Blaze involved multiple floors simultaneously
- a "chimney effect" combined with very high fuel loading led to temperatures exceeding 1,000°C in spots.
- the **unprotected perimeter steel columns above the 17th floor heated**



# Windsor tower, Spain

## 12<sup>th</sup> Feb 2005

**The building was under renovation relating to fire protection:**

- New exterior emergency stairwells
- Updating existing utilities (compartmentation improvements to utilities, stairwells, floors and basement)
- Sprinkler retrofitting
- Full curtain wall replacement, including fireproofing of the perimeter steel columns.



**This was only partially complete at the time of the fire.**

# Windsor tower, Spain

## 12<sup>th</sup> Feb 2005


- This triggered progressive collapses.
- 1<sup>st</sup> east face of the 21st floor at 3hrs into the fire
- 2<sup>nd</sup> upper sections around floors 20-25 shortly after
- 3<sup>rd</sup> south mid-sections of 17-20 appx 1 hour after that
- Debris from these falls thought to have cracked the 17th-floor transfer slab, aiding downward fire spread.
- Aluminum used in the curtain wall melted, "fire drops" propelled downward spread



# Windsor tower, Spain

## 12<sup>th</sup> Feb 2005

- Below the 17th floor, **protected steel held**, but unprotected spots (e.g., 9th floor south/west sides) buckled
- The concrete core and internal columns redistributed loads, preventing further failure.



Upper floor  
conditions



Lower floor  
conditions

# Windsor tower, Spain

12<sup>th</sup> Feb 2005



Upper  
floors



Lower floor:  
damage



21th Floor

17th Floor

# Windsor tower, Spain

## 12<sup>th</sup> Feb 2005

Fire protection system	At time of construction (1970s Spanish code)	At time of fire (under refurbishment)
Compartmentation	X	Under construction, <b>but not fully compartmentalised</b>
firestopping between cladding & Structure	X	Under construction
Protection of steel	X	17 <sup>th</sup> floor + above: NO 18 <sup>th</sup> floor, part complete 4-15 <sup>th</sup> floor: Complete (except 9 and 15)
Sprinkler system	X	Being retrofitted
Fire alarm system	YES	YES



**Buckling at floor 9**

- Smoke spread
- Flame spread
- Risk of structural collapse





Problems mitigated:

- **Smoke spread**
- **Flame spread**
- **Structural collapse**



What this means IRL:


- Safe egress for occupants
- Safer entry for fire fighters
- Low risk of structural collapse
- Building performs as it is expected during a fire



**Passive fire is needed all throughout the building.**


**Active fire protection IS NOT a SUBSTITUTE for passive fire**

**Passive AND active fire protection WORK TOGETHER to create a safe building.**




You can design the best system  
in the world, but if it's not  
installed correctly...

what you get won't match what  
you planned.



**FDNY COMMISSIONER DANIEL NIGRO**  
*“This fire took its toll on our city.”*

**A Brazilian court has sentenced four people to lengthy prison terms over the deaths of 242 club-goers in a fire during a party in 2013.**







Firestop Contractors International Association

## DIIM Model



National Fireproofing  
Contractors Association

Maintaining a chain of  
accountability &  
responsibility  
is imperative for fire

It is how we avoid:

*“That’s not my job...”*



Passive fire  
Saves Lives ——.

Contact — .

**Dr Gabrielle Peck** Ph.D., MRSC

Technical Director

Email: [gabby@FCIA.org](mailto:gabby@FCIA.org)

Phone: +44 7362299609

Web: [www.FCIA.org](http://www.FCIA.org) [www.NFCA-online.org](http://www.NFCA-online.org)

