2014

BARRIER MANAGEMENT SYMPOSIUM

THE ISSUE



Anne Guglielmo, Associate Director

Standards Interpretation Group Engineering Department

The Joint Commission









BARRIER MANAGEMENT SYMPOSIUM

- Program Developers:
 - **□** Joint Commission
 - □ Firestop Contractors International Association
 - Underwriters Laboratories
- Participating Organizations:
 - American Society for Healthcare Engineering
 - □ AWCI & Gypsum Institute
 - ☐ Fire Damper Industry
 - ☐ Fire Rated Glazing Industry
 - National Concrete Masonry Association



Standard/NPSG	2012 Non Compliance	2014 Non Compliance (1 st Six Months)
RC.01.01.01	61%	55%
LS.02.01.20	51%	54%
IC.02.02.01	42%	47%
EC.02.05.01	34%	46%
LS.02.01.10	46%	45%
EC.02.03.05	40%	44%
LS.02.01.30	39%	43%
LS.02.01.35	34%	38%
EC.02.06.01	35%	36%
MM.03.01.01	35%	33%



#2 LS.02.01.20 EP 13

EP	Assembly Affected	Issue
1	Door	Locking
2	Door	Swing
3	Horizontal exits	Requirements
4	Outside stair	Building protection
5	Horizontal exit: door	Requirements
6	Horizontal exit	Fire jump
8	Exit	Discharge
9	Stair doors	Hold open
10	Doors	New boiler rooms, mechanical rooms, and heater rooms



#5 LS.02.01.10 EP5-7&9

EP	Assembly Affected	Issue
1	Building type	Construction type
3	Rated walls	Features
4	Rated walls	Openings
5	Rated doors	Features
6	Doors	Protective plates
7	Doors	Coverings
8	Ducts	Penetration
9	Penetrations	Firestopping



#7 LS.02.01.30

EP	Assembly Affected	Issue
1	Vertical openings	Protection
2	Hazardous areas	Walls & doors
3	Gift shop	Protection
6	Corridor partitions	Features
7	Corridor walls, new	Limit transfer of smoke
8	Fire windows in corridor walls	Features
9	Corridor doors	Features
10	Corridor doors	Plates
11	Corridor doors	Features



#7 LS.02.01.30

EP	Assembly Affected	Issue
12	Corridor walls	Openings
16	Smoke barriers	Features
18	Smoke barriers	Features
19	Smoke barriers	Features
20	Smoke barriers	Duct penetrations
21	Smoke barriers	Damper protection
22	Smoke barriers; smoke doors	Window opening rating
23	Smoke barriers doors	Features
24	Exit stair	Rating

LS.02.01.50

EP	Assembly Affected	Issue
8	Linen & waste chute inlet doors	Protection
9	Linen & waste chute inlet & discharge doors	Features
10	Linen & trash chutes discharge door	Features
11	Linen & waste chutes discharge	Separation



DEPARTMENT OF ENGINEERING 630 792 5900

George Mills, MBA, FASHE, CEM, CHFM, CHSP Director

Anne Guglielmo, CFPS, LEED, A.P., CHSP Engineer

John Maurer, CHFM, CHSP Engineer

> James Woodson, P.E., CHFM Engineer

> > **OPEN Engineer Position**



Copyright, The Joint Commission

THE JOINT COMMISSION DISCLAIMER

- These slides are current as of 8/13/2014. The Joint Commission reserves the right to change the content of the information, as appropriate.
- These slides are only meant to be cue points, which were expounded upon verbally by the original presenter and are not meant to be comprehensive statements of standards interpretation or represent all the content of the presentation. Thus, care should be exercised in interpreting Joint Commission requirements based solely on the content of these slides.
- These slides are copyrighted and may not be further used, shared or distributed without permission of the original presenter or The Joint Commission.



2014

BARRIER MANAGEMENT SYMPOSIUM

THE ISSUE



Anne Guglielmo
Engineering Department
The Joint Commission

